

PHOTO 56855/60




FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5

3/9
Acoustic Displacement




FIG. 6




FIG. 8




FIG. 7

09755895 06401
T04050" 96855/60




FIG. 9




FIG. 9A




FIG. 9B

0975895-050401




FIG. 10




FIG. 11




FIG. 12




FIG. 13




FIG. 14

09755895-050404




FIG. 15




FIG. 16

FIG. 15




FIG. 17




FIG. 18

FIG. 17